

Technical Bulletin No. TB251208-1

TECHNICAL BULLETIN

Title: Correcting Incorrect Wiring of Blue Wire on the BAR6 – Units Labeled Service Code 38

Date: December 8, 2025

Bulletin Number: TB251208-1

Affected Units: BAR6 Series - Service Code Beginning with 38

Issue:

BAR6 units with **Service Code beginning with 38** due to a **factory wiring error**: the **blue wire is connected to the L2 terminal** instead of the correct **T2 terminal**.

Action Required:

Before applying power to the unit, perform the following steps carefully:

1. **Locate the blue wire** currently connected to the L2 terminal.
2. **Carefully remove** the blue wire from the L2 terminal.
3. **Reconnect the blue wire** to the correct **T2 terminal**, as shown in the image below.
4. **Double-check all connections** for accuracy.
5. **Apply power** and verify that the unit operates normally.

Contact Tech Support if additional assistance is required.

