


# Exploded View

**Model**           BAH7-42-15 (25K)

**ComfortStar®**

Service code:    25K



EX_ID	Spare Parts Code	Part Name(EN)	Qty.	Price	Remarks
1	12223000005909	Side board ass	2.0		
2	12223100000243	Supporting board	1.0		
3	12200104000032	Fan	1.0		
4	11301805000012	Motor Mounting bolt	4.0		
5	11002015020572	Brushless DC Motor	1.0		
6	12123000000464	Motor installation board ass'y	1.0		
7	12923000000028	Grille	1.0		
8	11301002000001	Stainless steel bolts	8.0		
9	12223000001097	Top cover assembly	1.0		
10	15823000004429	Condenser ass'y	1.0		
11	15423000006078	Throttle assembly	1.0		
12	15423000003178	Stop valve ass'y	1.0		
13	15423000006060	Suction pipe ass'y	1.0		
13.1	15427000007112	Fusible plug assembly	1.0		
13.2	17400516001308	Pressure switch	1.0		
14	15423000006081	4-way valve ass'y	1.0		
14.1	15123000010937	Pipe joint ass'y	1.0		
14.2	15423000006070	4-way valve assembly	1.0		
14.2.1	15500216002943	4-way valve ass'y	1.0		
14.2.2	17400516001309	Pressure switch	1.0		
15	15500508001115	Accumulator cylinder	1.0		
16	12223000005895	Base assembly	1.0		
17	11102010002098	Fixed speed scroll compressor	1.0		
18	17223000011009	E-part box assembly	1.0		
18.1	12223000018130	Installation plate of electric parts subassembly	1.0		
18.2	17123000A04385	Outdoor main control board assembly	1.0		
18.3	17400103000150	Capacitor	1.0		
18.4	11203502000032	AC contactor	1.0		
19	12223000016090	Side panel assembly	1.0		
20	12223000A05994	Side panel assembly	1.0		
21	17400513006835	Discharge Temperature switch	1.0		

22	11201007003446	Room Temperature Sensor	1.0		
23	11201007005723	Pipe Temperature Sensor	1.0		
24	17402001000040	Compressor electric heater	1.0		