



Exploded View

Model LUC5-18-15 (0FS)

Service code: 0FS

ComfortStar®



EX_ID	Spare Parts Code	Part Name(EN)	Qty.	Price	Remarks
-------	------------------	---------------	------	-------	---------

1	12223000010753	Side Panel Assembly	1.00		
2	12223000002193	Side Panel Assembly	1.00		
3	11201708000008	Terminal	1.00		
4	12223000002125	Air Duct Assembly	1.00		
5	17223000009202	Electrical Control Box Assembly	1.00		
5.1	17123000009757	Indoor Unit Main Control Board	1.00		
5.2	12223000002167	Mounting Plate	1.00		
6	11203103000141	Linear Transformer	1.00		
7	12223000002231	Side Panel Assembly	1.00		
8	12100304000011	Orientation Line	1.00		
9	12223000002356	Chassis Assembly	1.00		
10	12223000001943	Drainage Pan Supporting Board	2.00		
11	12223000010761	Support Bar Assembly	1.00		
12	12223000010756	Clamp	2.00		
13	12223000001213	Drain Pan	1.00		
14	12223000010789	Cover Plate Assembly	1.00		
15	12223000010766	Drainage Pan Supporting Board	2.00		
16	12123000000099	Drain Pan Assembly	1.00		
17	12223000000028	Fixing Board Of Water Collector	2.00		
18	15500402000023	Seal Plug	2.00		
19	12223000000417	Support Bar	1.00		
19	12223000010761	Support Bar Assembly	1.00		
20	12223000002002	Cover board	1.00		
21	11301230000002	Screw	2.00		
22	15823000006563	Evaporator Assembly	1.00		
22.1	15223000000167	Outlet Pipe Assembly	1.00		
22.2	15423000004539	Evaporator Inlet Pipe Assembly	1.00		
22.3	15823000004401	Evaporator	2.00		
22.4	15500210000968	Two-Way Pipeline Throttle Valve	1.00		
22.5	15500220000031	Valve Plug	1.00		
22.6	12100901000010	Seal Ring	1.00		
22.7	15500302000014	Flange joint	1.00		
22.8	15500402000188	Nut	1.00		
23	11301002000673	Hexagon Head Bolt Assembly	3.00		

24	12223000001932	Motor Holder Assembly	3.00		
25	12223000001992	Motor Holder	1.00		
27	11002012003968	Single Phase Asynchronous Motor	1.00		
28	12200101000018	Wind Turbine Parts	1.00		
29	15500302000006	Flange joint	1.00		
30	17400103000152	Compressor Capacitor	1.00		
31	12223000002177	Clamp	1.00		