


Exploded View

Model BAH6-18-15 (38L)
Service code: 38L

ComfortStar®



EX_ID	Spare Parts Code	Part Name(EN)	Qty.	Price	Remarks
1	802935000006	Cover net	1		
3	802401300058	Outdoor motor	1		
4	802919900009	Axial-flow fan	1		

5	801235000247	Top cover assembly	1		
6	801535000086	Condenser assembly	1		
6.1	801635000318	Condenser inlet pipe assembly	1		
6.2	801635000316	Condenser output pipe assembly	1		
7	801235000162	Rear side-panel	2		
8	801235000137	Support board	3		
9	801235000163	Left side-panel	2		
10	801635000226	Four way valve assembly	1		
11	801635000235	Suction air pipe weld assembly	1		
12	801605000010	Gas-liquid separator	1		
13	801635000317	High pressure valve assembly	1		
14	803335000038	electric control box components	1		
14.1	801306300008	Electronic control board	1		
14.2	802405F00015	High pressure switch	1		
14.3	802405F00005	Low pressure switch	1		
14.4	802301500061	Condenser temperature sensor (T3)	1		
14.5	802301500055	Ambient temperature sensor (T4)	1		
14.6	802300400150	Exhaust temperature sensor (T5)	1		
14.7	802300400092	Return temperature sensor (TH)	1		
14.8	801600100065	Solenoid valve	1		
14.9	802300100261	AC contactor	1		
14.10	802401000033	Compressor capacitor	1		
15	801235000116	Top panel	1		
16	801235000245	Bottom side panel	1		
17	801235000170	Chassis assembly	1		
18	801402100069	Compressor	1		