


Exploded View

Model LUC32-18-15 (29Z)
Service code: 29Z

ComfortSi



EX_ID	Spare Parts Code	Part Name(EN)	Qty.	Price
1	601235000044	Chassis assembly	1	
2	601235000045	Upper Front Panel Adhesive Assembly	1	
3	601235000046	Lower Front Panel Adhesive Assembly	1	

4	601235000035	Piping Cover Plate Adhesive Assembly	1	
5	601235000047	Filter Mesh Import Plate	1	
6	601235000043	Filter Net Cover Plate	1	
7	601235000057	Middel Connecting Plate	1	
8	6015350A0002	Evaporator and Water Pan Assembly	1	
8.1	601135000007	Main Water Pan Assembly	1	
8.2	601135000008	Vice Water Pan Assembly	1	
8.3	601544000094	Evaporator component	1	
8.3.1	601235000039	Rear Evaporator Sealing Plate Assembly	1	
8.3.2	601535000105	Evaporator Assembly	1	
8.3.3	601235000053	Evaporator Connection Plate Assembly	1	
8.3.4	601630000418	Flute-shaped Tube Assembly	1	
8.3.5	601235000041	Frant Evaporator Sealing Plate Assembly	1	
8.3.6	601636000115	Distributor Assembly	1	
8.3.7	601235000040	Evaporator Drainage Plate Assembly	1	
9	601235000007	Support Plate	1	
10	603335000002	Electrical Control Box Assembly	1	
10.1	601336000041	Main control board	1	
10.2	602311300003	Linear Transformer	1	
10.3	601235000022	Electrical Control Board Mounting Plate	1	
11	601235000004	Terminal Block Mounting Plate Assembly	1	
11.1	602404700070	24V Terminal Block	1	
11.2	601235000006	Terminal Block Mounting Plate	1	
11.3	602404700054	Terminal Block for Power Cables	1	
11.4	601235000005	Terminal Block Mounting Plate	1	
12	602403100016	Slotted Capacitor	1	
13	601235000054	Fan Motor and Wheel Assembly	1	
13.1	602401300024	AC fan motor	1	
13.2	601235000049	Impeller Scroll Assembly	1	
14	602301800002	Refrigerant leakage detector	1	
	602301500063	Temperature sensor assembly(T1)	1	
	602301500083	Temperature sensor assembly(T2)	1	



— 1

Remarks

[illegible]